


**Monitor Work Station SIT / STAND 4-axis, Profile Attachment 40
(Set)**
6MHM75100S40IT(0)(0)(0)



PARTNR (Part #)	PROFILE (Profile)	ROT (Rotation / °)	ROT1 (Rotation / °)	ROT2 (Rotation / °)	WEIGHT (Weight / g)	CTN (Customs Tariff Number)	ID (pA Number)
6MHM75100S40IT	I	0	0	0	9200	73269098	147834